

STUDY ON LIQUEFACTION INDUCED PERMANENT GROUND DISPLACEMENTS

By

Masanori HAMADA¹⁾

Susumu YASUDA²⁾

Ryuji ISOYAMA³⁾

and

Katsutoshi EMOTO¹⁾

November 1, 1986

¹⁾ Faculty of Marine Science and Technology, Tokai University, Shimizu, Japan

²⁾ Dept. of Civil Engineering, Kyushu Institute of Technology, Kitakyushu, Japan

³⁾ Japan Engineering Consultants, Co., Ltd., Tokyo, Japan

Acknowledgement

The research presented in this paper had been conducted by the research committee organized by the Association for the Development of Earthquake Prediction in Japan for the "Study on Resistant Design of Buried Pipes Against Soil Liquefaction during Earthquakes."

Our deepest appreciation to Prof. K. Kubo of Saitama University, the chairman of the committee, for his excellent leadership and strong support to the research. Our appreciation is also extended to other members of the committee for their efficacious discussions during committee meetings, and for their germane recommendations on how to carry out the research. The authors firmly believe that the successful achievement of this research project would not have been accomplished without their good cooperation.

Furthermore, we express our sincere thanks to Mr. J. Ikeda, the secretariat of Association for the Development of Earthquake Prediction, who contributed greatly to the management of the committee and to the preparation of this paper.

CONTENTS

1 . Introduction	1
2 . Permanent Ground Displacements in Noshiro City during The 1983 Nihonkai-Chubu Earthquake	3
2 . 1 Method of measurement	3
2 . 2 Permanent ground displacements and earthquake damage	5
2 . 2 . 1 Measured permanent ground displacements	5
2 . 2 . 2 Ground failures and permanent ground displacements	9
2 . 2 . 3 Damage to houses and buried pipes, and permanent ground displacements	12
2 . 3 Study of the causes of permanent ground displacements	12
3 . Permanent Ground Displacements in Niigata City during The 1964 Niigata Earthquake	20
3 . 1 Method of measurement	20
3 . 2 Permanent ground displacements and earthquake damage	21
3 . 2 . 1 Measured permanent ground displacements	21
3 . 2 . 2 Damage to revetments, bridge piers, foundation piles, etc.	24
(1) Damage to Shinano River revetment	25
(2) Damage to the Hakusan power substation	25
(3) Collapse of the Showa Bridge	26
(4) Damage to the retaining wall of access road on the left bank of the Showa Bridge	28
(5) Damage to substructure of the Yachiyo Bridge	28
(6) Damage to RC piles	30
3 . 3 Study on the causes of permanent ground displacements	31
3 . 3 . 1 Section A-A' (left bank in Kawagishi-cho)	31
3 . 3 . 2 Section B-B' (Hakusan Park—Showa Bridge)	31
3 . 3 . 3 Section C-C' and Section E-E' (left bank of Bandai Bridge—Niigata Railway Station)	32
3 . 3 . 4 Section D-D' (near Nishibori Street—left bank of Yachiyo Bridge)	32
4 . Analysis of Relationship between Magnitudes of Permanent Ground Displacements, and Geological and Topographical Conditions	36
4 . 1 Study on factors influencing magnitudes of permanent ground displacements	36
4 . 2 Regression analysis of magnitudes of permanent ground displacements	41

5 . Correlation Analysis of Damage Rate to Houses and Buried Pipes with Permanent Ground Displacements and Strains	43
5 . 1 Correlation of damage rate to houses and buried pipes, with the magnitude of permanent ground displacements	43
5 . 2 Correlation of damage rate to buried pipes and ground cracks, with permanent ground strains ...	46
5 . 2 . 1 Calculation of permanent ground strains	46
5 . 2 . 2 Correlation of damage rate to buried pipes and ground cracks with the permanent strains	49
6 . Numerical Analyses of the Failure Processes of Foundation Piles and Buried Pipe during Earthquakes	51
6 . 1 Numerical analyses of RC piles damaged by The 1964 Niigata earthquake	51
6 . 1 . 1 Stresses in piles caused by inertia forces	52
6 . 1 . 2 Stresses in piles caused by permanent ground displacement	53
6 . 1 . 3 Consideration of the cause of the damage to the piles	57
6 . 2 Numerical analysis of buried steel gas pipe damaged by The 1983 Nihonkai-Chubu earthquake	58
6 . 2 . 1 Damage to welded steel gas pipe and the permanent ground displacements measured in the vicinity	59
6 . 2 . 2 Numerical analysis of the deformation of the welded steel gas pipe	59
7 . Conclusion	61
Appendix I Accuracy of Measurement of Permanent Ground Displacements in Noshiro City	64
Appendix II Accuracy of Measurement of Permanent Ground Displacement in Niigata City	68
Appendix III Factor of Liquefaction Resistance, F_L and Index of Liquefaction Potential, P_L	69
Appendix IV Summary of Landslides in The Vicinity of The Upper Van Norman Lake during The 1971 San Fernando Earthquake	70
Appendix V Soil Layer Profile of 27 Sections in Noshiro City	73
References	87